Approved For Release 2001/08/08: CIA-RDP78-04007A001100030011-5

Spurce Reference

### WINDOW GRILLES

#1 BPS Memorandum to OS

28 December 1956

Requests OS decision on grilles for windows and other unprotected accesses.

#2 BPS Memorandum to OS

9 January 1957

The Architect intends to have fixed windows on the ground, first, second, and seventh floors.

STATINTL

#23

Memorandum for the Record

OCI Security Staff advises that no grilles will be necessary for windows within the OCI restricted area provided that the windows are not accessible from adjoining ledges or roofs.

#4 OS Memorandum to BPS

12 February 1957

Security requirements for the protection of windows by means of grilles or an alarm system or both. Generally all openings with an access available of 18° or less must be protected.

#5 OS Memorandum to BPS

27 May 1957

Specific security requirements for doors and windows are enumerated for each floor having means of exterior access.

#6 BPS Memorandum to OS

14 August 1957

The Architect has been informed of security requirements for grilles, the cost of which will not be covered in the construction contract.

#7 BPS Memorandum for the Record

16 August 1957

An account of a meeting in which the DD/S supported the position of the OS on the protection of windows by grilles and alarms. The Architect will design the grilles and provide for their installation. If there is sufficient money for their installation they will be provided by the contractor.

# Approved For Release 2001/08/08 : CIA-RDP78-04007A001100030011-5

#8

Survey Branch Memorandum to A&TS

23 August 1957

Cost of window grilles may have to be planned for in the OS Budget for Calendar Year 1960.

### Approved For Release 2001/08/08: CIA-RDP78-04007A001100030011-5

Chiof, Swilding Manning Staff, CI

Director of Jacurity

May Mendquarters Politing Exterior Door out Mindow Protection 27 may 1957

- 1. The previous assemble on verious retters included under this general rubject were solutioned as statements of security principles to be used as guides in the preliminary stages of the dealgning and planning of the building. With determinations on to design now beving been made, and somewhat detailed plans now consisted, more specific security requirements can be presented.
- 2. Specific accuraty requirements necessarily are based upon actual design and construction features, and any change in these features as now submitted would require a reconsideration of the security requirements which should apply to them.
  - 3. 18th the propont unferstandings
  - wintows;
  - b. That the non-igency custodict oreas in the rear of the ground floor, and the cafeteria area in the rear of the first floor, are to be separated from the rest of the building by solid marchey walls, with the only accord from then to the rest of the building through decrease which can be escurely locked when not controlled by grands;
  - c. That there will be no access to the inner courts except through the controlled Agency space in the building, onl no custodial or other non-Agency space will face on the courts; and,
  - d. That the exterior unlia of the second and soventh floors are to be virtually uslid glass panels,

the security requirements as to window and door openings in the building wells are so follows:

20 6 C

### GROUD AND FIRST FLYORS

- of those of the exterior windows, with the exception of those of the defeterie and non-Agency custodial areas, are to be protected by matel grilles or bare installed on the inside.
- (2) To grilles or bers are necessary on the exterior walls of the custodial or cafetaria cross; nor are they necessary on the windows of the offices facing the inner courts.
- (3) No grillos or bers are necessary on the colld gloss penols, windows, or doors at the main entrace on the first floor between the main lebby and the outside of the outranseway, since it is contemplated that this area will be under continuous guard control.
- (4) All doors in the exterior walls of these floors are to be equipmed with alarm devices, the type of which will be specified separately.
- (5) The exterior windows of all Secure Armas located on these two floors are to be equipped, in addition to the grilles or bers, with almos devices, the type of which will be specified reparately.

#### SECOND PLOCES

- (1) All decrease leading from this floor to the wide expanse of concepts or other material which is the roof of the first floor, are to be cominced with alarm devices, the two of which will be specified separately.
- (2) The outside walls of this floor are the type which cannot be rade to meet the requirements for the walls of a focure week. Hence, the location of any Secure Areas at the walls of this floor must be evoided. Should it be accessery to locate any Secure Area at these walls, then a separate well meeting Secure Area requirements would have to be constructed incide the glass penals.
- (3) There is no requirement that grilles or bors be installed on the glass panels which constitute the windows of this floor, provided that the space is not devoted to Secure Irons or highly sensitive activities.

### Approved Fo Belease 2001/08/08 : CIA-RDP78-0400(A) 01100030011-5

## THIRD TO SETT PACES. TOTALINE.

- (1) There is no requirement that grilles or bars be installed on the winious of these floors, except in the care of fedure Areas.
- (2) The wintows of any Secure Areas located on those floors are to be equipped with grilles or bars of the type specified above, but they need not be equipped with alarse.

### SERVEDH PIDER:

- (1) Any decrease leading from this floor to the nerrow terrose satisfic the walls (the reaf of the Sixth Place), are to be comissed with alarm devices of a type which will be specified later.
- (2) The outside walks of this floor, similar to those of the Second Floor, are planned as virtually solid glass powers, and the security requirements are the second second Floor.

### Transport Challes 12

- (1) All deers leading from the penthouses to the roof are to be equipped with alarm devices of a type which will be epecified later.
- (?) There are no special cocurity requirements as to any wirdows which may be placed in the rent houses.

SHEFFIELD EDUARDS

25X1A9a

OS: PhSD/SB: . /csm(21 May 1957)

Distribution:

25X1A9a

Orig. & 1 - Addressee

1 - SB Chrono

1 - Reading

Total Maria Constant

Approved Fc Release 2001/08/08 : CIA-RDP78-04007 001100030011-5

16 August 1957

MIMORANDIM for the Record

SURJECT: Orilles and Alarms on Windows

1. A meeting was held today in the office of the DD/S to discuss various security matters in connection with construction of the new CIA headquarters building at Langley, Virginia. Present were Col. White, DD/S; Col. Edwards, Director of Security; Nr. Chief, Building DD/S; Col. Edwards, Director of Security; Nr. Chief, Building Planning Staff; Nr. DD/S Ideison Officer on new building and Management Assistant/BPS; and the undersigned.

2. One of the matters discussed was the item of window protection. The DD/S supported the position of the Office of Security as follows:

- a. All outside windows on the Ground and First Floors (with exception of cafetoria and non-Agency custodial areas) are to be grilled.
- b. All windows of Secure Areas are to be grilled. This requirement specifically includes Secure Areas located on the Second and Seventh Floors where the walls are glass panels.
- c. All windows of Secure Areas located on the Ground and First Floors are to have electric devices attached to them which will sound an alarm in the Central Control Room when unauthorized entrance is attempted through them.
- 3. The DD/S agreed that the Architect-Engineer should design the grilles required on windows and that the construction contract shall include grille anchors placed in the mesonry work. In addition, the plans and specifications will provide for an alternate item of the grilles themselves; then, if there is sufficient money for their installation they will be provided by the general contractor; if not enough money, we will have a firm figure from which we will know how much we will have to provide from other funds for a separate contract.

4. The electric alarms for windows requiring them will be covered in the construction contract.

25X1A9a

25X1A

25X1A

Security Assistant Building Planning Staff

Approved Fd Delease 2001/08/08: CIA-RDP78-040074001100030011-5

עווויני /

Oniof, Figure Committy Division, ASES

Chicf, Survey Spanish

Advance Dudget Tlanning Window Crilles for New Headquarters Fuilding

- proposes that the cost of Similating the electify protection of window grilles on the ground and direct floors of the new Headquarters hailding may have to be charged against the CS indjet.
- 2. By recorandom of 14 August 1977, the Chief of the Building Plenning Starf stated that the cost of the grilles was not included in the new building budget. Lut on 16 August 1957, the DD/S informally stated that the furnishing and installing of this equipment could be included as an alternate in the proposal for bids for the general construction contract, so that if the crownt of the bids is law enough it might be possible to include the gallies; otherwise, the remay would have to come from case other source.
- 3. If the cost is to be changed to 03, it would not be incurred with after the completion of the general contract, or not until the letter part of calcular year 1960.
- based on probably 500 window eponings of 4'rd0' sine on the first floor, a total square footage of 20,000; and 250 h'rd' openings on the ground floor, or 2,000 square feet. Espanded retal grilles cost about (4.75 a square feet (65 figure in Jensery 1057), and for the 22,000 square feet this would come to (30,500. Henover, instead of our need expanded notal grilles, it is contemplated that the architects will design grilles to fit into the general building design, we can great that this probably would double the cost.

25X1A9a

25X1A9a

OS: PhySD/SB/

mlb (23 Aug 57)

Distribution:

O&L - Addressee

1 - SB Chrono

1 - Reading